


**REPORT  
FOR  
HAZARDOUS MATERIALS IDENTIFICATION  
STUDY  
AT THE  
WHITINSVILLE SOCIAL LIBRARY  
WHITINSVILLE, MASSACHUSETTS**



PROJECT NO: 225 536.00

Survey Dates:  
August 18-19, 2025

CONDUCTED BY:  
**UNIVERSAL ENVIRONMENTAL CONSULTANTS**  
12 Brewster Road  
Framingham, MA 01702



August 20, 2025

Mr. Dave Hurley  
Senior Project Manager  
Leftfield Project Management  
225 Franklin Street  
Boston, MA 02110

Reference: Report for Hazardous Materials Identification Study  
Whitinsville Social Library, Whitinsville, MA

Dear Mr. Hurley:

Thank you for the opportunity for Universal Environmental Consultants (UEC) to provide professional services.

Enclosed please find the report for the hazardous materials identification study at the Whitinsville Social Library, Whitinsville, MA.

Please do not hesitate to call should you have any questions.

Very truly yours,

Universal Environmental Consultants

A handwritten signature in blue ink, appearing to read "Ammar M. Dieb", is written over a horizontal line.

Ammar M. Dieb  
President

UEC:\225 536.00\Report.DOC

Enclosure

## **INTRODUCTION:**

Universal Environmental Consultants (UEC) has been providing comprehensive asbestos services since 2001 and has completed projects throughout New England. We have completed projects for a variety of clients including commercial, industrial, municipal, public, and private schools. We maintain appropriate asbestos licenses and staff with a minimum of thirty-seven years of experience.

UEC was contracted by the Town of Northbridge to conduct the following services at Whitinsville Social Library, Whitinsville, Massachusetts:

- Asbestos Containing Materials (ACM) determination inspection and sampling.
- Polychlorinated Biphenyls (PCB's)-Electrical Equipment and Light Fixtures inspection.
- PCB's in Caulking inspection.
- Lead Based Paint (LBP) inspection.
- Oil Tanks.

The scope of work included the inspection of accessible ACM, collection of bulk samples from materials suspected to contain asbestos, determination and quantities of types of ACM found and cost estimates for remediation. *A comprehensive survey per the Environmental Protection Agency (EPA) NESHAP regulation including destructive testing would be required prior to any renovation or demolition activities.*

Bulk samples analysis for asbestos was performed using the standard Polarized Light Microscopy (PLM) Method in accordance with EPA standard. Bulk samples were collected by a Massachusetts licensed asbestos inspectors, Mr. Jason Becotte (AI-034963). Samples analyzed by a Massachusetts licensed laboratory Asbestos Identification Laboratory, Woburn, MA.

Samples results are attached.

## **FINDINGS:**

### **Asbestos Containing Materials (ACM):**

The regulations for asbestos inspection are based on representative sampling. It would be impractical and costly to sample all materials in all areas. Therefore, representative samples of each homogenous area were collected and analyzed or assumed.

All suspect materials were grouped into homogenous areas. By definition, a homogenous area is one in which the materials are evenly mixed and similar in appearance and texture throughout. A homogeneous area shall be determined to contain asbestos based on findings that the results of at least one sample collected from that area show that asbestos is present in an amount greater than 1 percent in accordance with EPA regulations. Per the Department of Environmental Protection (DEP) any amount of asbestos found must be disposed as asbestos.

No additional suspect or accessible ACM were found during this survey. Hidden ACM may be found during the renovation and demolition activities.

### **Number of Samples Collected:**

Fifty-four (54) bulk samples were collected from materials suspected of containing asbestos, including:

### **Type and Location of Suspect Material**

1. Blown-in insulation at attic
2. Blown-in insulation at attic
3. Ceiling paint coating at first floor stacks
4. Ceiling paint coating at first floor stacks
5. Stone floor mortar at basement stacks
6. Stone floor mortar at basement stacks
7. Cement electric panel at basement
8. Cement electric panel at basement

9. Chimney exhaust cement at boiler room
10. Chimney exhaust cement at boiler room
11. Cement floor coating at first floor office
12. Cement floor coating at first floor office
13. Cork flooring at second floor
14. Cork flooring at second floor
15. Yellow mastic for cork flooring at second floor
16. Yellow mastic for cork flooring at second floor
17. Beige 12" x 12" vinyl floor tile at basement break room
18. Beige 12" x 12" vinyl floor tile at basement break room
19. Yellow mastic for beige 12" x 12" vinyl floor tile at basement break room
20. Yellow mastic for beige 12" x 12" vinyl floor tile at basement break room
21. Blue 12" x 12" vinyl floor tile at rear stairwell
22. Blue 12" x 12" vinyl floor tile at rear stairwell
23. Yellow mastic for blue 12" x 12" vinyl floor tile at rear stairwell
24. Yellow mastic for blue 12" x 12" vinyl floor tile at rear stairwell
25. Joint compound at first floor rear hallway
26. Joint compound at second floor elevator lobby
27. 2' x 4' Suspended acoustical ceiling tile at first floor elevator lobby
28. 2' x 4' Suspended acoustical ceiling tile at second floor elevator lobby
29. Plaster
30. Plaster
31. Plaster
32. Plaster
33. Plaster
34. Plaster
35. Plaster
36. Block coating at interior of exterior wall
37. Block coating at interior of exterior wall
38. Exterior window glazing caulking
39. Exterior window glazing caulking
40. Exterior window glazing caulking
41. Exterior window framing caulking
42. Exterior window framing caulking
43. Exterior window framing caulking
44. Tar on cement deck at original building flat roof
45. Tar on cement deck at original building flat roof
46. Tar on cement deck at original building flat roof
47. Paper under slate at pitched roof
48. Paper under slate at pitched roof
49. Wall flashing tar at original building roof parapet
50. Wall flashing tar at original building roof parapet
51. Roof wall caulking at original building to addition
52. Roof wall caulking at original building to addition
53. Pipe penetration caulking at addition roof
54. Pipe penetration caulking at addition roof

**Sample Results:**

**Type and Location of Suspect Material**

**Sample Result**

- |  |                      |
|--|----------------------|
| 1. Blown-in insulation at attic                | No Asbestos Detected |
| 2. Blown-in insulation at attic                | No Asbestos Detected |
| 3. Ceiling paint coating at first floor stacks | No Asbestos Detected |
| 4. Ceiling paint coating at first floor stacks | No Asbestos Detected |
| 5. Stone floor mortar at basement stacks       | No Asbestos Detected |

|   |                      |
|---|----------------------|
| 6. Stone floor mortar at basement stacks                                      | No Asbestos Detected |
| 7. Cement electric panel at basement  | 25% Asbestos         |
| 8. Cement electric panel at basement  | 25% Asbestos         |
| 9. Chimney exhaust cement at boiler room                                      | 15% Asbestos         |
| 10. Chimney exhaust cement at boiler room                                     | No Asbestos Detected |
| 11. Cement floor coating at first floor office                                | No Asbestos Detected |
| 12. Cement floor coating at first floor office                                | No Asbestos Detected |
| 13. Cork flooring at second floor   | No Asbestos Detected |
| 14. Cork flooring at second floor   | No Asbestos Detected |
| 15. Yellow mastic for cork flooring at second floor                           | No Asbestos Detected |
| 16. Yellow mastic for cork flooring at second floor                           | No Asbestos Detected |
| 17. Beige 12" x 12" vinyl floor tile at basement break room                   | No Asbestos Detected |
| 18. Beige 12" x 12" vinyl floor tile at basement break room                   | No Asbestos Detected |
| 19. Yellow mastic for beige 12" x 12" vinyl floor tile at basement break room | No Asbestos Detected |
| 20. Yellow mastic for beige 12" x 12" vinyl floor tile at basement break room | No Asbestos Detected |
| 21. Blue 12" x 12" vinyl floor tile at rear stairwell                         | No Asbestos Detected |
| 22. Blue 12" x 12" vinyl floor tile at rear stairwell                         | No Asbestos Detected |
| 23. Yellow mastic for blue 12" x 12" vinyl floor tile at rear stairwell       | No Asbestos Detected |
| 24. Yellow mastic for blue 12" x 12" vinyl floor tile at rear stairwell       | No Asbestos Detected |
| 25. Joint compound at first floor rear hallway                                | No Asbestos Detected |
| 26. Joint compound at second floor elevator lobby                             | No Asbestos Detected |
| 27. 2' x 4' Suspended acoustical ceiling tile at first floor elevator lobby   | No Asbestos Detected |
| 28. 2' x 4' Suspended acoustical ceiling tile at second floor elevator lobby  | No Asbestos Detected |
| 29. Plaster   | No Asbestos Detected |
| 30. Plaster   | No Asbestos Detected |
| 31. Plaster   | No Asbestos Detected |
| 32. Plaster   | No Asbestos Detected |
| 33. Plaster   | No Asbestos Detected |
| 34. Plaster   | No Asbestos Detected |
| 35. Plaster   | No Asbestos Detected |
| 36. Block coating at interior of exterior wall                                | No Asbestos Detected |
| 37. Block coating at interior of exterior wall                                | No Asbestos Detected |
| 38. Exterior window glazing caulking  | 2% Asbestos          |
| 39. Exterior window glazing caulking  | 2% Asbestos          |
| 40. Exterior window glazing caulking  | No Asbestos Detected |
| 41. Exterior window framing caulking  | 2% Asbestos          |
| 42. Exterior window framing caulking  | 2% Asbestos          |
| 43. Exterior window framing caulking  | 2% Asbestos          |
| 44. Tar on cement deck at original building flat roof                         | No Asbestos Detected |
| 45. Tar on cement deck at original building flat roof                         | No Asbestos Detected |
| 46. Tar on cement deck at original building flat roof                         | No Asbestos Detected |
| 47. Paper under slate at pitched roof   | No Asbestos Detected |
| 48. Paper under slate at pitched roof   | No Asbestos Detected |
| 49. Wall flashing tar at original building roof parapet                       | 5% Asbestos          |
| 50. Wall flashing tar at original building roof parapet                       | 5% Asbestos          |
| 51. Roof wall caulking at original building to addition                       | No Asbestos Detected |
| 52. Roof wall caulking at original building to addition                       | No Asbestos Detected |
| 53. Pipe penetration caulking at addition roof                                | No Asbestos Detected |
| 54. Pipe penetration caulking at addition roof                                | No Asbestos Detected |

**Observations and Conclusions:**

The condition of ACM is very important. ACM in good condition does not present a health issue unless it is disturbed. Therefore, it is not necessary to remediate ACM in good condition unless it will be disturbed through renovation, demolition, or other activity.

1. Cement electric panel at basement was found to contain asbestos.
2. Chimney exhaust cement at boiler room was found to contain asbestos.
3. Exterior window glazing caulking was found to contain asbestos.
4. Exterior window framing caulking was found to contain asbestos.
5. Hidden pipe and hard joint insulation was assumed to exist and assumed to contain asbestos.
6. Wall flashing tar at original building roof parapet was found to contain asbestos.
7. All other suspect materials were found not to contain asbestos. Hidden ACM may be found during renovation and demolition activities.

**Polychlorinated Biphenyls (PCB's)-Electrical Equipment and Light Fixtures:**

***Observations and Conclusions***

Visual inspection of various equipments such as light fixtures, thermostats, exit signs and switches was performed for the presence of PCB's and mercury. Ballasts in light fixtures were assumed not to contain PCB's since there were labels indicating that "No PCB's" was found. Tubes in light fixtures, thermostats, signs, and switches were assumed to contain mercury. It would be very costly to test those equipments and dismantling would be required to access. Therefore, the above-mentioned equipment should be disposed of in an EPA approved landfill as part of the demolition project.

**PCB's in Caulking Material:**

***Observations and Conclusions***

Building caulking was assumed to contain PCB's. PCB's are manmade chemicals that were widely produced and distributed across the country from the 1950s to 1977 until the production of PCB's was banned by the US Environmental Protection Agency (EPA) law which became effective in 1978. PCB's are a class of chemicals made up of more than 200 different compounds. PCB's are non-flammable, stable, and good insulators so they were widely used in a variety of products including electrical transformers and capacitors, cable and wire coverings, sealants and caulking, and household products such as television sets and fluorescent light fixtures. Because of their chemical properties, PCB's are not very soluble in water, and they do not break down easily in the environment. PCB's also do not readily evaporate into air but tend to remain as solids or thick liquids. Even though PCB's have not been produced or used in the country for more than 30 years, they are still present in the environment, in the air, soil, and water and in our food. EPA requires that all construction waste including caulking be disposed of as PCB's if PCB's level exceeds 50 mg/kg (ppm). An abatement plan might also be required.

EPA does not require testing.

**Lead Based Paint (LBP):**

***Observations and Conclusions***

LBP was assumed to exist on various painted surfaces. All LBP activities performed, including waste disposal, should be in accordance with applicable Federal, State, or local laws, or ordinances, codes, or regulations governing evaluation and hazard reduction. In the event of discrepancies, the most protective requirements prevail. These requirements can be found in OSHA 29 CFR 1926-Construction Industry Standards, 29 CFR 1926.62-Construction Industry Lead Standards, 29 CFR 1910.1200-Hazards Communication, 40 CFR 261-EPA Regulations.

According to OSHA, any amount of LBP triggers compliance.

**Oil Tanks:**

***Observations and Conclusions:***

There are two (2) house size oil tanks in the boiler room.

**COST ESTIMATES:**

The cost includes removal and disposal of all accessible ACM, other hazardous material, and an allowance for removal of inaccessible or hidden ACM that may be found during the renovation project.

| Location | Material              | Approximate Quantity | Cost Estimate (\$) |
|----------|-----------------------|----------------------|--------------------|
| Basement | Cement Electric Panel | 8 SF                 | 500.00             |

| Location  | Material                              | Approximate Quantity | Cost Estimate (\$)   |
|---|---------------------------------------|----------------------|----------------------|
|   | Chimney Exhaust Cement                | 2 SF                 | 500.00               |
| Boiler Room   | Oil Tanks                             | 2 Total              | 4,500.00             |
| Various Locations   | Miscellaneous Hazardous Materials     | Unknown              | 5,000.00             |
|   | Hidden Pipe and Hard Joint Insulation | Unknown              | 15,000.00            |
| Exterior  | Windows                               | 52 Total             | 52,000.00            |
|   | Roof Flashing                         | 100 LF               | 1,500.00             |
| Fees for Design, Construction Monitoring and Air Sampling |                                       |                      | 26,000.00            |
| <b>Total:</b>   |                                       |                      | <b>\$ 105,000.00</b> |

**DESCRIPTION OF SURVEY METHODS AND LABORATORY ANALYSES:**

Asbestos samples were collected using a method that prevents fiber release. Homogeneous sample areas were determined by criteria outlined in EPA document 560/5-85-030a. Samples were analyzed using EP/600/R-93/116 Method.

**LIMITATIONS AND CONDITIONS:**

This report has been completed based on visual and physical observations made and information available at the time of the site visits, as well as an interview with the Owner's representatives. This report is intended to be used as a summary of available information on existing conditions with conclusions based on a reasonable and knowledgeable review of evidence found in accordance with normally accepted industry standards, state, and federal protocols, and within the scope and budget established by the client. Any additional data obtained by further review must be reviewed by UEC and the conclusions presented herein may be modified accordingly.

This report and attachments, prepared for the exclusive use of Owner for use in an environmental evaluation of the subject site, are an integral part of the inspections and opinions should not be formulated without reading the report in its entirety. No part of this report may be altered, used, copied, or relied upon without prior written permission from UEC, except that this report may be conveyed in its entirety to parties associated with Owner for this subject study.



## Asbestos Identification Laboratory.

165 New Boston St., Ste 227  
Woburn, MA 01801  
781-932-9600

Web: [www.asbestosidentificationlab.com](http://www.asbestosidentificationlab.com) Email:  
[mikemanning@asbestosidentificationlab.com](mailto:mikemanning@asbestosidentificationlab.com)



**Batch: 140547**

Project Information

*Social Library,  
Whitinsville,  
MA*

*Method: BULK PLM ANALYSIS,  
EPA/600/R-93/116*

Ammar Dieb  
Universal Environmental Consultants  
12 Brewster Road  
Framingham, MA 01702

Dear Ammar Dieb,

Asbestos Identification Laboratory has completed the analysis of the samples from your office for the above referenced project. The Analysis Method is BULK PLM ANALYSIS, EPA/600/R-93/116. The information and analysis contained in this report have been generated using the EPA /600/R-93/116 Method for the Determination of Asbestos in Bulk Building Materials. Materials or products that contain more than 1% of any kind or combination of asbestos are considered an asbestos containing building material as determined by the EPA. This Polarized Light Microscope (PLM) technique may be performed either by visual estimation or point counting. Point counting provides a determination of the area percentage of asbestos in a sample. If the asbestos is estimated to be less than 10% by visual estimation of friable material, the determination may be repeated using the point counting technique. The results of the point counting supersede visual PLM results. Results in this report only relate to the items tested. This report may not be used by the customer to claim product endorsement by NVLAP or any other U.S. Government Agency.

The EPA recommends you should assume vermiculite contains asbestos and not to disturb it. Airborne asbestos fibers present a health risk through inhalation, so the first step is to not disturb the material, which could release fibers into the air. If you disturb the insulation, you may inhale some asbestos fibers. The degree of health risk depends on how much and how often this occurred. If you choose to remove the vermiculite insulation, this work should be done by a trained and accredited asbestos abatement contractor that is separate and independent from the company that performed the assessment of the vermiculite insulation to avoid any conflict of interest. Link: "<https://www.epa.gov/asbestos/my-attic-has-vermiculite-insulation-it-am-i-risk-should-i-take-it-out> | US EPA"

Laboratory results represent the analysis of samples as submitted by the customer. Information regarding sample location, description, area, volume, etc., was provided by the customer. Information provided by the customer can affect the validity of results. Asbestos Identification Laboratory is not responsible for sample collection activities or analytical method limitations. Unless notified in writing to return samples, Asbestos Identification Laboratory discards customer samples after 30 days. Samples containing subsamples or layers will be analyzed separately when applicable. Reports are kept at Asbestos Identification Laboratory for three years. All customer information will be maintained in confidentiality. This report shall not be reproduced, except in full, without the written consent of Asbestos Identification Laboratory.

- NVLAP Lab Code: 200919-0
- Massachusetts Certification License: AA000208
- State of Connecticut, Department of Public Health Approved Environmental Laboratory Registration Number: PH-0142
- State of Maine, Department of Environmental Protection Asbestos Analytical Laboratory License Number: LB-0078(Bulk) LA-0087(Air)
- State of Rhode Island and Providence Plantations. Department of Health Certification: AAL-121
- State of Vermont, Department of Health Environmental Health License AL934461

Thank you Ammar Dieb for your business.

Michael Manning  
Owner/Director

Social Library,  
 Whitinsville,  
 MA

| FieldID<br>LabID | Material               | Location                 | Color  | Non-Asbestos %                 | Asbestos %                |
|------------------|------------------------|--------------------------|--------|--------------------------------|---------------------------|
| 1<br>1581920     | Blown-in Insulation    | Attic                    | brown  | Cellulose 95<br>Non-Fibrous 5  | None Detected             |
| 2<br>1581921     | Blown-in Insulation    | Attic                    | brown  | Cellulose 95<br>Non-Fibrous 5  | None Detected             |
| 3<br>1581922     | Ceiling Paint Coating  | 1st Fl. Stacks           | white  | Non-Fibrous 100                | None Detected             |
| 4<br>1581923     | Ceiling Paint Coating  | 1st Fl. Stacks           | white  | Non-Fibrous 100                | None Detected             |
| 5<br>1581924     | Stone Floor Mortar     | Basement Stacks at Steel | gray   | Non-Fibrous 100                | None Detected             |
| 6<br>1581925     | Stone Floor Mortar     | Basement Stacks at Steel | gray   | Non-Fibrous 100                | None Detected             |
| 7<br>1581926     | Cement Electric Panel  | Basement Electric Corner | gray   | Non-Fibrous 75                 | Detected<br>Chrysotile 25 |
| 8<br>1581927     | Cement Electric Panel  | Basement Electric Corner | gray   | Non-Fibrous 75                 | Detected<br>Chrysotile 25 |
| 9<br>1581928     | Chimney Exhaust Cement | Boiler Room              | gray   | Non-Fibrous 85                 | Detected<br>Chrysotile 15 |
| 10<br>1581929    | Chimney Exhaust Cement | Boiler Room              | gray   | Non-Fibrous 100                | None Detected             |
| 11<br>1581930    | Cement Floor Coating   | 1st Floor Office         | gray   | Non-Fibrous 100                | None Detected             |
| 12<br>1581931    | Cement Floor Coating   | 1st Floor Office         | gray   | Non-Fibrous 100                | None Detected             |
| 13<br>1581932    | Cork Flooring          | 2nd Fl. West Side        | tan    | Cellulose 20<br>Non-Fibrous 80 | None Detected             |
| 14<br>1581933    | Cork Flooring          | 2nd Fl. West Side        | tan    | Cellulose 20<br>Non-Fibrous 80 | None Detected             |
| 15<br>1581934    | Yellow Mastic          | 2nd Fl. West Side        | yellow | Non-Fibrous 100                | None Detected             |
| 16<br>1581935    | Yellow Mastic          | 2nd Fl. West Side        | yellow | Non-Fibrous 100                | None Detected             |

Sampled: August 19, 2025      Received: August 19, 2025      Analyzed: August 20, 2025

Wednesday 20 August

Analyzed by:



Batch: 140547

Social Library,  
 Whitinsville,  
 MA

| FieldID<br>LabID | Material        | Location               | Color  | Non-Asbestos %                                  | Asbestos %    |
|------------------|-----------------|------------------------|--------|---|---------------|
| 17<br>1581936    | Beige 12x12 VFT | Basement Breakroom     | tan    | Non-Fibrous 100                                 | None Detected |
| 18<br>1581937    | Beige 12x12 VFT | Basement Breakroom     | tan    | Non-Fibrous 100                                 | None Detected |
| 19<br>1581938    | Yellow Mastic   | Basement Breakroom     | multi  | Non-Fibrous 100                                 | None Detected |
| 20<br>1581939    | Yellow Mastic   | Basement Breakroom     | multi  | Non-Fibrous 100                                 | None Detected |
| 21<br>1581940    | Blue 12x12 VFT  | Rear Stairwell         | gray   | Non-Fibrous 100                                 | None Detected |
| 22<br>1581941    | Blue 12x12 VFT  | Rear Stairwell         | gray   | Non-Fibrous 100                                 | None Detected |
| 23<br>1581942    | Yellow Mastic   | Rear Stairwell         | yellow | Non-Fibrous 100                                 | None Detected |
| 24<br>1581943    | Yellow Mastic   | Rear Stairwell         | yellow | Non-Fibrous 100                                 | None Detected |
| 25<br>1581944    | Joint Compound  | 1st Fl. Rear Hallway   | white  | Non-Fibrous 100                                 | None Detected |
| 26<br>1581945    | Joint Compound  | 2nd Fl. Elevator Lobby | white  | Non-Fibrous 100                                 | None Detected |
| 27<br>1581946    | 2x4 SAT         | 1st Fl. Elevator Lobby | gray   | Fiberglass 40<br>Cellulose 40<br>Non-Fibrous 20 | None Detected |
| 28<br>1581947    | 2x4 SAT         | 2nd Fl. Elevator Lobby | gray   | Fiberglass 40<br>Cellulose 40<br>Non-Fibrous 20 | None Detected |
| 29<br>1581948    | Plaster         | Dumbwaiter Shaft       | gray   | Hair 5<br>Non-Fibrous 95                        | None Detected |
| 30<br>1581949    | Plaster         | Basement Stacks        | multi  | Non-Fibrous 100                                 | None Detected |
| 31<br>1581950    | Plaster         | Basement Breakroom     | multi  | Non-Fibrous 100                                 | None Detected |
| 32<br>1581951    | Plaster         | 1st Fl. Stacks         | multi  | Non-Fibrous 100                                 | None Detected |

Sampled: August 19, 2025 Received: August 19, 2025 Analyzed: August 20, 2025

Wednesday 20 August

Analyzed by:



Batch: 140547

Social Library,  
 Whitinsville,  
 MA

| FieldID<br>LabID | Material           | Location                   | Color | Non-Asbestos %                 | Asbestos %               |
|------------------|--------------------|----------------------------|-------|--------------------------------|--------------------------|
| 33<br>1581952    | Plaster            | 1st Fl. Stacks             | multi | Non-Fibrous 100                | None Detected            |
| 34<br>1581953    | Plaster            | 1st Fl. Office             | multi | Non-Fibrous 100                | None Detected            |
| 35<br>1581954    | Plaster            | 2nd Fl. West Side          | multi | Non-Fibrous 100                | None Detected            |
| 36<br>1581955    | Black Wall Coating | Interior of Exterior Walls | black | Non-Fibrous 100                | None Detected            |
| 37<br>1581956    | Black Wall Coating | Interior of Exterior Walls | black | Non-Fibrous 100                | None Detected            |
| 38<br>1581957    | Window Glass Glaze | Exterior Window            | multi | Non-Fibrous 98                 | Detected<br>Chrysotile 2 |
| 39<br>1581958    | Window Glass Glaze | Exterior Window            | multi | Non-Fibrous 98                 | Detected<br>Chrysotile 2 |
| 40<br>1581959    | Window Glass Glaze | Exterior Window            | multi | Non-Fibrous 100                | None Detected            |
| 41<br>1581960    | Window Frame Caulk | Exterior Window            | multi | Non-Fibrous 98                 | Detected<br>Chrysotile 2 |
| 42<br>1581961    | Window Frame Caulk | Exterior Window            | multi | Non-Fibrous 98                 | Detected<br>Chrysotile 2 |
| 43<br>1581962    | Window Frame Caulk | Exterior Window            | multi | Non-Fibrous 98                 | Detected<br>Chrysotile 2 |
| 44<br>1581963    | Tar on Cement Deck | Original Flat Roof Cut 1   | black | Non-Fibrous 100                | None Detected            |
| 45<br>1581964    | Tar on Cement Deck | Original Flat Roof Cut 2   | black | Non-Fibrous 100                | None Detected            |
| 46<br>1581965    | Tar on Cement Deck | Original Flat Roof Cut 3   | black | Non-Fibrous 100                | None Detected            |
| 47<br>1581966    | Paper Under Slate  | Pitched Roof               | black | Cellulose 75<br>Non-Fibrous 25 | None Detected            |
| 48<br>1581967    | Paper Under Slate  | Pitched Roof               | black | Cellulose 75<br>Non-Fibrous 25 | None Detected            |

Sampled: August 19, 2025 Received: August 19, 2025 Analyzed: August 20, 2025

Wednesday 20 August

Analyzed by:



Batch: 140547

Social Library,  
 Whitinsville,  
 MA

| FieldID<br>LabID | Material               | Location                       | Color | Non-Asbestos %  | Asbestos %               |
|------------------|------------------------|--------------------------------|-------|-----------------|--------------------------|
| 49<br>1581968    | Wall Flashing Tar      | Roof Parapet Original Building | black | Non-Fibrous 95  | Detected<br>Chrysotile 5 |
| 50<br>1581969    | Wall Flashing Tar      | Roof Parapet Original Building | black | Non-Fibrous 95  | Detected<br>Chrysotile 5 |
| 51<br>1581970    | Roof Wall Caulk        | Original Building to Addition  | brown | Non-Fibrous 100 | None Detected            |
| 52<br>1581971    | Roof Wall Caulk        | Original Building to Addition  | black | Non-Fibrous 100 | None Detected            |
| 53<br>1581972    | Pipe Penetration Caulk | Addition Roof                  | multi | Non-Fibrous 100 | None Detected            |
| 54<br>1581973    | Pipe Penetration Caulk | Addition Roof                  | multi | Non-Fibrous 100 | None Detected            |

Sampled: August 19, 2025 Received: August 19, 2025 Analyzed: August 20, 2025

Wednesday 20 August

Analyzed by:



Batch: 140547

# CHAIN OF CUSTODY

|   |
|---|
| Universal Environmental Consultants       |
| 12 Brewster Road                          |
| Framingham, MA 01702                      |
| Tel: (508) 628-5486 - Fax: (508) 628-5488 |
| adieb@uec-env.com                         |

PLM  
24-hour TAT

Town/City: Whitinsville, MA Building Name Social Library

| Sample | Description of Material | Sample Location          |
|--------|-------------------------|--------------------------|
| 1      | Blown-In Insulation     | Attic                    |
| 2      | l l                     | l l                      |
| 3      | ceiling Paint Coating   | 1st Fl. Stacks           |
| 4      | l l                     | l l                      |
| 5      | stone floor mortar      | Basement stacks at steel |
| 6      | l l                     | l l                      |
| 7      | cement electric Panel   | Basement electric corner |
| 8      | l l                     | l l                      |
| 9      | chimney exhaust cement  | Boiler Room              |
| 10     | l l                     | l l                      |
| 11     | cement floor coating    | 1st floor office         |
| 12     | l l                     | l l                      |
| 13     | Cork Flooring           | 2nd fl. west side        |
| 14     | l l                     |                          |
| 15     | Yellow mastic           |                          |
| 16     | l l                     |                          |
| 17     | Beige 12x12 VFT         | Basement Break Room      |
| 18     | l l                     |                          |
| 19     | Yellow mastic           |                          |
| 20     | l l                     |                          |

Reported By: Jason Becotte Date: 8-19-25  
 Received By: [Signature] Date: 8/19/25

Due Date: **24-Hours**

# CHAIN OF CUSTODY

PLM

|   |
|---|
| Universal Environmental Consultants       |
| 12 Brewster Road                          |
| Framingham, MA 01702                      |
| Tel: (508) 628-5486 - Fax: (508) 628-5488 |
| adieb@uec-env.com                         |

Town/City: Whitinsville, MA Building Name Social Library

| Sample | Description of Material | Sample Location            |
|--------|-------------------------|----------------------------|
| 21     | Blue 12x12 VFT          | Rear Stair well            |
| 22     |                         |                            |
| 23     | yellow mastic           |                            |
| 24     |                         |                            |
| 25     | Joint compound          | 1st fl. Rear hallway       |
| 26     |                         | 2nd fl. Elevator Lobby     |
| 27     | 2x4 SAT                 | 1st fl. elevator Lobby     |
| 28     |                         | 2nd fl. elevator Lobby     |
| 29     | Plaster                 | Dumb waiter shaft          |
| 30     |                         | Basement stacks            |
| 31     |                         | Basement Break room        |
| 32     |                         | 1st fl. Stacks             |
| 33     |                         | 1st fl. Stacks             |
| 34     |                         | 1st fl. office             |
| 35     |                         | 2nd fl. west side          |
| 36     | Black wall coating      | Interior of exterior walls |
| 37     |                         |                            |
| 38     | window Glass Glaze      | Exterior window            |
| 39     |                         |                            |
| 40     |                         |                            |

Reported By: Jason Beuthe Date: 8-19-25 Due Date: **24-Hours**

Received By: \_\_\_\_\_ Date: \_\_\_\_\_

# CHAIN OF CUSTODY

PLM

|  |
|--|
| <b>Universal Environmental Consultants</b>               |
| 12 Brewster Road   |
| Framingham, MA 01702                                     |
| Tel: (508) 628-5486 - Fax: (508) 628-5488                |
| <a href="mailto:adieb@uec-env.com">adieb@uec-env.com</a> |

Town/City: Whitinsville, MA Building Name Social Library

| Sample | Description of Material | Sample Location                |
|--------|-------------------------|--------------------------------|
| 41     | Window Frame caulk      | Exterior window                |
| 42     |                         |                                |
| 43     |                         |                                |
| 44     | Tar on cement deck      | Original Flat Roof cut 1       |
| 45     |                         | original Flat Roof cut 2       |
| 46     |                         | original Flat Roof cut 3       |
| 47     | Paper under slate       | Pitched Roof                   |
| 48     |                         |                                |
| 49     | wall Flashing tar       | Roof parapet original Building |
| 50     |                         |                                |
| 51     | Roof wall caulk         | original building to addition  |
| 52     |                         |                                |
| 53     | Pipe Penetration caulk  | addition Roof                  |
| 54     |                         |                                |
|        |                         |                                |
|        |                         |                                |
|        |                         |                                |
|        |                         |                                |
|        |                         |                                |
|        |                         |                                |
|        |                         |                                |

Reported By: Jason Beotte Date: 8-19-25

Due Date: **24-Hours**

Received By: \_\_\_\_\_ Date: \_\_\_\_\_